



Rehabilitation and Replacement of 136 no's of Sluice Gates and Their Hoisting Equipment's of 100 years old KRS Dam, Karnataka



By: Aditya Mishra, Dy. Director, Gates Design (E&NE), CWC Rahul Kumar Singh, Director, Gates Design(NW&S), CWC Vivek Tripathi, Chief Engineer, Design (E&NE), CWC



nora

INTERNATIONAL DAM SAFETY CONFERENCE



Salient Features of the KRS Dam (from KRS Sluices by M.C. Sampatiegner Book)

General				
River	Cauvery			
Location	Near Kannambadi Village of Srirangapattana taluk, Mandya Dist. Karnataka State.			
Year of Construction	1911 - 1931			
Geophysical Features				
Catchment Area	10,619 Sq.Kms.			
Nature of Catchment Area	The Malnad portion of the catchment is hilly and thickly wooded. It gets heavy rainfall mostly in the South-West monsoon.			
Climate	37.22 ⁰ C maximum			
Mean annual precipitation	160.96 Cms (63.37")			
10.12 October 2022 at Jainur Baiasthan (India)				





Annual yield at Dam site	189 TMCft.		
Geological features at dam site	Gneissic Granite with bands of horn-blend schist.		
Technical			
Length of the Dam	2.62 Kms. (8597 ft.)		
Height of the Dam above the River bed	130.8 ft.		
Gross storage capacity	49.452 TMC		
Live storage capacity	45.051 TMC		
Dead storage at RL 60 ft.	4.401 TMC		
(732.74 M or 2404 ft.)			
Lowest River bed level	714.45 M (2344 ft. MSL)		
FRL/MWL	752.489 M (2468.80 ft. MSL) –		
	124.80 ft. above River bed		





Type of Dam	Gravity Dam,	
	Stone masonry with surki mortar	
Purpose of project	Multi purpose	
Catchment Area	10,619 sq.km (4100 sq.miles)	
Maximum designed flood discharge	3,50,000 Cusecs	





Details of Sluice Gates for proposed Rehabilitation (from KRS Sluices by M.C. Sampatiegner Book)

Description	Туре	Size	No's
+103 Level Sluice Gates	 Fixed roller type Operated with Gantry (16T capacity) 	10'x 8'	48
+106 Level Sluice Gates	 Fixed roller type Operated with Gantry (16T capacity) 	8'x 12'	40
+114 Level Sluice Gates	Automatic gates	10'x 10'	48





Condition Assessment of Sluice Gates at EL +106, +106 and +114 Level

> Heavy Leakage through Sluice Gates

Corroded/Damaged Gates and Embedded Parts

Non Closure of Gates

Operational Difficulties



Leakage of Water


Corroded Top Seal (Made up of Bronze pad)



Broken Wheel












Status of Sluice Gates and before Rehabilitation work















Rehabilitation Measures

 Rehabilitation of Embedded Parts of EL +103 & +106 Level Sluice Gates










(Approved Drg No. HTMPL/KRS/106'/GATE/04)







Details of +103 & +106 Embedded Parts after rehabilitation (*from KRS Dam site erection*)






Replacement of Sluice Gates of EL +103 & +106 Level



Removal of +106 Old Gate (from KRS Dam site Erection of +106 New Gate (from KRS Dam site erection) erection)








Removal of +103 Level old Gate (from KRS Dam site erection)

Erection of +103 Level New Gate (*from KRS Dam site erection*)





Rehabilitation of Embedded Parts of EL +114 Level Sluice Gates



Details of Embedded parts of +114' Level Sluice Gates after Rehabilitation (Approved Drg No. HTMPL/KRS/114'/GATE/01 Sheet 1 of 2)








Embedded parts of +114' Level Sluice Gates after Rehabilitation (from KRS Dam site erection)





Replacement of Sluice Gates of EL +114 Level Sluice Gates







Key Achievements

of +103, +106 ice Gates Improvements of HM after Sluice Rehabilitation & +114 Sh The Replacement of all 136 numbers of sluice gate and their Hoisting equipment's at elevation +103', +106', +114' (except the combined trestle of +103 & +114, which is under progress) have been successfully achieved within budget and time schedule

Restored flood discharging capacity by preventing the leakages

Extended their useful lives by Reducing the Failures

Gate Operation without Difficulty





After Rehabilitation Sluice Gate Assessment



Leakages in +103' Level Sluice Gates before Leakage arrested +103' Level Gates after **Rehabilitation** (from KRS Dam site erection) *rehabilitation* (from KRS Dam site erection)







Leakages in +106' Level Sluice Gates before Rehabilitation (from KRS Dam site erection) Leakage arrested +106' Level Gates after rehabilitation (from KRS Dam site erection)







Leakages in +114' Level Sluice Gates before Rehabilitation (from KRS Dam site erection)

Leakage arrested +114' Level Gates after rehabilitation (from KRS Dam site erection)





Lesson Learnt in Rehabilitation of Sluice Gates

Rehabilitation Leve & +114 Le KRS Dam for Faced in 90 103, +1 Gates 1 T Challenges work of +1 Sluice

No provisions of Stoplogs there gate erection works were only be carried out when the water level is below the sill of the Gate

Existing Track Base is made up of cast iron material there welding will leads to the development of the Cracks

Due to the widespread pandemic of Corona Virus, the country is in the lock down condition which forced the project authorities to extend the project schedule and likely expenditure


Heritage structure, retaining of originality in architecture, aesthetics and the monumental ambience to be the upper most concern





Dam Rehabilitation & Improvement Project Central Water Commission

Acknowledgment













Backup Slide













